



NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY

Facility Inspected: Beth Ray Center For Academic Support

Inspection Date: 02/04/20 1:13 PM

Reinspect Date: 03/06/20 8:00 AM

A joint fire safety inspection of the facility listed above was performed by the Environmental Health & Safety - Fire and Life Safety Department and the Corvallis Fire Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately and no later than the scheduled reinspection date listed in the accompanying email. If you have any questions regarding this inspection, please email me. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Safety Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

* Annotates a deficiency identified by the Corvallis Fire Department..

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action so that all deficiencies have been corrected prior to the reinspection date.

Facilities Services Priority Codes:

Priority 1: items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: items are long term fixes that should be either added to an ongoing work list or to the capital improvement list for campus upgrades.

The due date is listed in the body of the Email. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Brian Lilley (EH&S - Fire and Life Safety) at brian.lilley@oregonstate.edu. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969.

Completed	Priority	Responsible Party	Location	Description	Code Reference	Notes
	2	Facilities Services	141	Repair exit door/hardware.	CFC 1008	Latch sticks and won't lock.
X	2	Department	364	"Remove combustible storage from mechanical, electrical, and boiler rooms."	CFC 315.3	
	2	Department	362A	Plug power strips directly into outlet. Do not chain one to another.	CFC 605.4.2	Discontinue plugging extension cord into power strip. Extension cords shall not be run under doors.
X	2	Department	324	Plug microwave into wall receptacle instead of extension cord or power strip.		
	2	Department	Throughout	Plug power strips directly into outlet. Do not chain one to another.	CFC 605.4.2	Discontinue plugging table recessed power strips into power strips. Recommendation: disable table recessed power strip and plug extra power strip directly into floor outlet, not into each other.
X	2	Facilities Services	400-5 Mechanical	"Remove combustible storage from mechanical, electrical, and boiler rooms."	CFC 315.3	Provide 4x8 taped off area for storage of air filters. Keep storage clear from electrical panels and 18" from sprinkler heads. Do not store excessive amounts.
	2	Facilities Services	Grounds	Address identification must be visible from the street (new installations - minimum number height = 6 inches).	CFC 505.1	Provide a monument sign.