

Building Manager: [Christine Pastorek, christine.pastorek@oregonstate.edu](mailto:christine.pastorek@oregonstate.edu)
 Assessment Date: 2/10/2021
 Assessment Number: **9968**
 Location: Gilbert Addition Entire
 Reinspection date: 3/26/2021

A joint fire safety inspection of the facility listed above was performed by the Environmental Health & Safety - Fire and Life Safety and the Corvallis Fire Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately and no later than the scheduled reinspection date noted with this report. If you have any questions regarding this inspection, please email Brian Lilley (EH&S - Fire and Life Safety) at brian.lilley@oregonstate.edu.

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

* Annotates a deficiency identified by the Corvallis Fire Department.

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health & Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action so that all deficiencies have been corrected prior to the reinspection date. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969.

Facilities Services Priority Codes:

Priority 1: items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: items are long term fixes that should be either added to an ongoing work list or to the capital improvement list for campus upgrades.

Comments:

Priority code	Standard in need of attention	Reg.Reference	Location	Resp	Observations & Recommendations	Date Corrected
1	Exit and exit access doors shall be marked by an approved exit sign readily visible from any direction of egress travel.	2019 OFC 1013.1	Throughout..	FS	Move south end exit signs downward to ensure visibility from main lab space: 2nd floor main lab 3rd floor main lab	3/25/2021
1	Provide approved exit door hardware and/or maintain exit door.	2019 OFC 1010	Throughout..	FS	Adjust fire doors to close properly: 2nd floor breezeway 3rd floor breezeway	3/25/2021

Priority code	Standard in need of attention	Reg.Reference	Location	Resp	Observations & Recommendations	Date Corrected
2	Stairwells shall be kept clear and not used for storage.	2019 OFC 1003.6	Stairwell:.	DEPT/FS	Remove yellow bin and cabinet base from stairway landing roof access.	3/25/2021
1	Provide a warning sign or EH&S placard on containers, cabinets and rooms.	2019 OFC 5003.5	4th Floor:Main Lab	DEPT DEPT	Provide flammable cabinet sticker for blue cabinet.	
2	Provide a warning sign or EH&S placard on containers, cabinets and rooms.	2019 OFC 5003.5	0011:inside	DEPT DEPT	Discontinue storing organic material (paper, cardboard. etc.) in same area as organic chemicals to prevent contamination.	3/25/2021
2	Additional Findings:		Throughout:.	FS FS	Repair/replace ceiling tiles. Rooms: Basement lobby (CORRECTED) 2nd and 3rd floor breezeway (CORRECTED) 418	
2	Additional Findings:		Main Lab:Hood 11	FS FS	Repair self-closing mechanism on chemical cabinet.	3/25/2021