

Building Manager: [Anthony Conrath, anthony.conrath@oregonstate.edu](mailto:anthony.conrath@oregonstate.edu)  
 Assessment Date: 7/12/2022  
 Assessment Number: **10583**  
 Location: Reser Stadium Entire  
 Reinspection date:

A joint fire safety inspection of the facility listed above was performed by the Environmental Health & Safety - Fire and Life Safety and the Corvallis Fire Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately and no later than the scheduled reinspection date noted with this report. If you have any questions regarding this inspection, please email Brian Lilley (EH&S - Fire and Life Safety) at [brian.lilley@oregonstate.edu](mailto:brian.lilley@oregonstate.edu).

**Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.**

\* Annotates a deficiency identified by the Corvallis Fire Department.

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health & Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action so that all deficiencies have been corrected prior to the reinspection date. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969.

**Facilities Services Priority Codes:**

**Priority 1:** items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

**Priority 2:** items should be corrected within the five-week period before the scheduled reinspections.

**Priority 3:** items are long term fixes that should be either added to an ongoing work list or to the capital improvement list for campus upgrades.

**Comments:**

<b>Priority code</b>	<b>Standard in need of attention</b>	<b>Reg.Reference</b>	<b>Location</b>	<b>Resp</b>	<b>Observations &amp; Recommendations</b>	<b><a href="#">Date Corrected</a></b>
2	Fire doors shall close from the full-open position and latch automatically.	2019 OFC 705.2.4	424:door	DEPT	Bathroom door is rated as a fire door and will not close properly.&nbsp;  The door seems to get stuck on the carpet.	

**Priority  
code**

**Standard in need of attention**

Reg.Reference

Location

Resp

Observations & Recommendations

[Date Corrected](#)



Room 424

2

Repair painted/corroded sprinkler head.

NFPA 13

Outside:Suit 321

DEPT

Missing sprinkler sleeve and paint on sprinkler head.



Outside suite 321.


Priority code	Standard in need of attention	Reg.Reference	Location	Resp	Observations & Recommendations	Date Corrected
---------------	-------------------------------	---------------	----------	------	--------------------------------	----------------

2	All sprinkler valves shall be supervised/locked in the open position, accessible, and unobstructed. Door to control room shall be identified.	2019 OFC 901.4.6.1 and 903.3.8.4	430:entrance	DEPT	Provide "CONTROL VALVE" sticker for door into room 430.	
---	---	----------------------------------	--------------	------	---	--



Room 430

2	Discontinue use of extension cord not plugged directly into an approved receptacle. Do not chain together.	2019 OFC 604.5.1	101:inside	DEPT	Discontinue plugging orange extension cord (to TV on wall) and yellow extension cord (running along opposite wall of TV) into power strips. Provide a power strip with longer cable instead.	
---	--	------------------	------------	------	--	--



Room 101

**Priority  
code**

**Standard in need of attention**

Reg.Reference

Location

Resp

Observations & Recommendations

[Date Corrected](#)

3

Additional Findings:

351:ceiling

DEPT

Replace ceiling tile in room.



Room 351