

NOTICE OF FIRE SAFETY INSPECTION

OREGON STATE UNIVERSITY



Facility Inspected: NAVY ROTC ARMORY

Inspection Date: 01/16/2015

Reinspect Date: 02/24/2015

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection, please phone me at 737-3066. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Prevention Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

** Annotates a deficiency identified by OSU Environmental health and safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.

Facilities Services Priority Codes:

Priority 1: (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: (p2) items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Jim Patton (Corvallis Fire Department) at 737-3066. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969. MS Excel format is available upon request.

Completed?	Priority	Responsible Party	Location	Description	Code Reference	Notes
------------	----------	-------------------	----------	-------------	----------------	-------

Completed?	Priority	Responsible Party	Location	Description	Code Reference	Notes
	1	DEPT	Near 121	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES.	CFC 315.2.2, 1027, http://surplus.oregonstate.edu/spr	Remove material from hallway
	2	DEPT	0120	Maintain clearance between combustibles and heat producing appliances.	CFC 305.1	Clean out toaster
	2	EHS	Near 203C	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	CFC 906.2, NFPA 10	
	2	DEPT	0113A	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	CFC 605.4, 605.5	Heaters shall plug directly into outlet. Remove extension cord from permanent use.

Completed?	Priority	Responsible Party	Location	Description	Code Reference	Notes
	2	DEPT	Junior Classroom	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	CFC 605.4, 605.5	Orange cord
	2	DEPT	Near 202B	Maintain clearance between combustibles and heat producing appliances.	CFC 305.1	Clean out toaster