

NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY



Facility Inspected: Crew Facility
 Inspection Date: 06/19/18 11:18 AM
 Reinspect Date: 07/30/18 8:00 AM

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection, please phone me at 737-3066. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Prevention Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

** Annotates a deficiency identified by OSU Environmental health and safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.

Facilities Services Priority Codes:

Priority 1: (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: (p2) items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Jim Patton (Corvallis Fire Department) at 737-3066. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969. MS Excel format is available upon request.

Completed	Priority	Responsible Party	Location	Description	Code Reference	Notes
	2	Department	Old Training Building (Underfloor)	I'm not very comfortable with charging a golf cart under the old training facility since the area is not protected by drywall, etc... Can we please look at a different location for this process? Thanks!		Please forward along to responsible organization.
	2	Facilities Services	Old Training Building (Upstairs)	Provide/maintain exit sign.	CFC 1011.1	Install a combo EXIT/Emergency light over the secondary exterior exit. Power is available.
X	2	EH&S	Old Training Building (Upstairs)	"Extinguishers shall be visible or signed, easily accessible, mounted with the bottom not less than 4 inches nor the top more than 4 feet above the floor."	"CFC 906.9, NFPA 10, ADA"	Relocate fire extinguisher to railing by stairs.

X	2	Department	Old Training Building (Closet)	"Cords shall not be affixed to, or extend through, walls, ceilings, floors, under doors, and shall not be subject to physical damage."	CFC 605.4.3	Cord running through wall.
X	2	Department	Main Boat Storage Facility	Resecure hatch to under floor area.		
X	1	Department	Main Boat Storage Facility	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	"CFC 605.4, 605.5"	Permanently remove the extension cords to the exterior training tank lights
X	2	EH&S	Main Boat Storage Facility (Shop)	Remove old fire extinguisher on work bench.		
X	2	EH&S	Main Boat Storage Facility	"Extinguishers shall be visible or signed, easily accessible, mounted with the bottom not less than 4 inches nor the top more than 4 feet above the floor."	"CFC 906.9, NFPA 10, ADA"	Relocate fire extinguisher to nearer the main entry (concealed behind door)
	2	Facilities Services	Exterior Fire Water Tanks	"Fire protection or detection systems shall be extended, altered, or repaired as necessary to maintain protection."	CFC 901.6	Repair floats on tanks to prevent overflowing.
X	2	Department	Main Facility Boat Storage Area	Don't store rec fire container inside with ash or burnt wood.		
X	2	Department	Main Facility Boat Storage Area	Provide approved safety container for flammable liquids.	CFC 5003.9.10	Discard all flammable storage containers without approved lids/valves
X	2	Department	Various Throughout	"Portable Ladders are OSHA approved and in good condition, steps and side rail joints tight"	"OSHA, Division 2 requirement"	Discard old wooden ladder unless OSHA approved (indicated on ladder)
X	2	Department	Main Facility Hallway	"Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES."	"CFC 315.3.2, 1030.3"	Remove posters from hallway.
	2	Department	Main Facility Laundry Room	Laundry dryers shall be properly vented to the outside and free of lint build-up.	IMC 504	Have dryer vents professionally cleaned annually and semi-annually clean out where the vent connects with the dryer.
X	2	EH&S	Various Throughout	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	