

NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY

Facility Inspected: Crop Science Building
 Inspection Date: 06/12/18 1:49 PM
 Reinspect Date: 07/23/18 8:00 AM

A fire safety inspection of the facility listed above was performed by the EH&S Fire and Life Safety Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection, please email me. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Safety Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

** Annotates a deficiency identified by OSU Environmental health and safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.

Facilities Services Priority Codes:

Priority 1: (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: (p2) items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Jim Patton (Fire and Life Safety) at jim.patton@oregonstate.edu. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969. MS Excel format is available upon request.

| Completed | Priority | Responsible Party | Location | Description | Code Reference | Notes |
|-----------|----------|-------------------|----------|---|--------------------------------|---|
| X | 2 | Department | Near 153 | "Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES." | "CFC 315.3.2, 1030.3" | Remove carts and cardboard from hallway. |
| | 2 | Department | Room 130 | Remove small fire extinguisher. | | |
| X | 2 | Department | Room 38A | Laboratory Safety Quick Reference Guide posted in each lab area. (These can be obtained from EH&S) | "OSHA, Division 2 requirement" | |
| X | 2 | Department | Room 009 | Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable. | "CFC 605.4, 605.5" | |
| X | 2 | EH&S | Room 002 | Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years. | "CFC 906.2, NFPA 10" | |
| | 1 | Department | Near 253 | "Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES." | "CFC 315.3.2, 1030.3" | Remove coat rack and wheeled cart from hallway. |
| X | 2 | Department | Room 221 | Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable. | "CFC 605.4, 605.5" | White cord to coffee maker |