



NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY

Facility Inspected: Gill Coliseum
 Inspection Date: 09/24/20 2:45 PM
 Reinspect Date:

A joint fire safety inspection of the facility listed above was performed by the Environmental Health & Safety - Fire and Life Safety and the Corvallis Fire Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately and no later than the scheduled reinspection date listed in the accompanying email. If you have any questions regarding this inspection, please email me. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Safety Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

* Annotates a deficiency identified by the Corvallis Fire Department..

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action so that all deficiencies have been corrected prior to the reinspection date.

Facilities Services Priority Codes:

Priority 1: items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: items are long term fixes that should be either added to an ongoing work list or to the capital improvement list for campus upgrades.

The due date is listed in the body of the Email. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Brian Lilley (EH&S - Fire and Life Safety) at brian.lilley@oregonstate.edu. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969.

Completed	Priority	Responsible Party	Location	Description	Code Reference	Notes
	1	Department	Old Press Box	Combustible material shall not be allowed to accumulate in buildings or structures.	2019 OFC 304.1	Decrease combustible storage (e.g. newspapers, trash, paint cans, etc.).
	1	Department	218	Extension cords and flexible cords shall not be a substitute for permanent wiring.	2019 OFC 604.5	Discontinue plugging display refrigerator into extension cord.
	1	Facilities Services	207	Missing sprinkler sleeve.		
	1	Department	61B	Fire doors shall close from the full-open position and latch automatically.	2019 OFC 705.2.4	Discontinue propping open fire door.
	1	Department	23	Discontinue use of extension cord not plugged directly into an approved receptacle. Do not chain together.	2019 OFC 604.5.1	Discontinue use of extension cord. Replace with UL Listed power tap.
	1	Department	Men's Soccer Lounge	Extension cords and flexible cords shall not be a substitute for permanent wiring.	2019 OFC 604.5	Discontinue plugging power strip into extension cord and plugging refrigerator into power strip.