

Building Manager: [Robyn Panico, robyn.panico@oregonstate.edu](mailto:robyn.panico@oregonstate.edu)
 Assessment Date: 3/8/2022
 Assessment Number: **10554**
 Location: Magruder Hall Entire
 Reinspection date:

A joint fire safety inspection of the facility listed above was performed by the Environmental Health & Safety - Fire and Life Safety and the Corvallis Fire Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately and no later than the scheduled reinspection date noted with this report. If you have any questions regarding this inspection, please email Brian Lilley (EH&S - Fire and Life Safety) at brian.lilley@oregonstate.edu.

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

* Annotates a deficiency identified by the Corvallis Fire Department.

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health & Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action so that all deficiencies have been corrected prior to the reinspection date. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969.

Facilities Services Priority Codes:

Priority 1: items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: items are long term fixes that should be either added to an ongoing work list or to the capital improvement list for campus upgrades.

Comments:

Priority code	Standard in need of attention	Reg.Reference	Location	Resp	Observations & Recommendations	Date Corrected
2	A means of egress shall be free from obstructions that would prevent its use. Combustible materials shall not be stored in exit pathways.	2019 OFC 1031.3 and 315.3.2	208:exit	DEPT	Maintain egress pathway by: - Swapping bookshelf with skeleton display - Removing ALL chairs from pathway - Removing ALL combustible material (boxes) from pathway	

**Priority
code**

Standard in need of attention

Reg.Reference

Location

Resp

Observations & Recommendations

[Date Corrected](#)



Room 208

2

Discontinue use of extension cord not plugged directly into an approved receptacle. Do not chain together.

2019 OFC 604.5.1

110:Large Animal Radiology

DEPT

Discontinue plugging orange extension cord into power strip. Also, mount power strip to wall according to manufacturer's instruction OR lay power strip on floor. Do not let power strip hang freely.



110 Large Animal Radiology

Priority code	Standard in need of attention	Reg.Reference	Location	Resp	Observations & Recommendations	Date Corrected
2	Compressed gas cylinders shall be secured with one or more restraints to prevent falling.	2019 OFC 5303.5.3	0110:Across from	DEPT	Provide enough restraints to properly secure gas cylinders to wall.	



Gas Cylinder Room