



NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY

Facility Inspected: Magruder Hall
 Inspection Date: 03/18/20 11:14 AM
 Reinspect Date:

A joint fire safety inspection of the facility listed above was performed by the Environmental Health & Safety - Fire and Life Safety Department and the Corvallis Fire Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately and no later than the scheduled reinspection date listed in the accompanying email. If you have any questions regarding this inspection, please email me. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Safety Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

* Annotates a deficiency identified by the Corvallis Fire Department..

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action so that all deficiencies have been corrected prior to the reinspection date.

Facilities Services Priority Codes:

Priority 1: items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: items are long term fixes that should be either added to an ongoing work list or to the capital improvement list for campus upgrades.

The due date is listed in the body of the Email. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Brian Lilley (EH&S - Fire and Life Safety) at brian.lilley@oregonstate.edu. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969.

Completed	Priority	Responsible Party	Location	Description	Code Reference	Notes
	1	Department	147D	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	"CFC 605.4, 605.5"	
	1	Facilities Services	245	"Provide cover plates on all electrical outlets, switches, and junction boxes."	CFC 605.6	
	1	EH&S	240B	Provide laboratory safety caution sign for room.		
	2	Facilities Services	239	Provide automatic door closer for room.		
	1	Department	251	Plug power strips directly into outlet. Do not chain one to another.	CFC 605.4.2	Discontinue using extension cord into power strip.
	1	Department	Throughout	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Discontinue propping open fire doors.
	1	Facilities Services	Near 273	Provide/maintain exit sign.	CFC 1011.1	
	1	Facilities Services	269	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Fire door does not latch.
	1	Department	259	Discontinue using temporary yellow power boxes and remove.		
	1	Department	259	Do not hang red cables off sprinkler piping.		
	2	Facilities Services	260C	"Required fire walls, occupancy separation walls, and draft stops shall be maintained."	CFC 703.1	Fully enclose electrical room.

1	Department	110 A & C	Keep emergency disconnect panel clear from obstructions.		
2	Facilities Services	Large animal holding area inside and outside room / room 110G / near 271	Replace missing sprinkler sleeves.		
2	Facilities Services	Chemo Prep (1st Floor New Construction)	Required fire walls, occupancy separation walls, and draft stops shall be maintained. - OFC 703.1		Seal holes in room and around bio safety cabinet vent.
1	Department	1006 (Cardiology Suite)	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	"CFC 605.4, 605.5"	
1	Department	2002	Provide/maintain exit sign.	CFC 1011.1	Provide knockout directional arrow indicating which direction exit is located for sign.
1	Department	2010	Plug power strips directly into outlet. Do not chain one to another.	CFC 605.4.2	Discontinue using extension cord into power strip.
1	Department	2013	Remove tape from sprinkler head.		
2	Department	Throughout	Replace/repair ceiling tiles missing or with large holes.		