

Building Manager: [Debbi-Lee Mott, deb.mott@oregonstate.edu](mailto:deb.mott@oregonstate.edu)
 Assessment Date: 3/31/2022
 Assessment Number: **10561**
 Location: Memorial Union Entire
 Reinspection date:

A joint fire safety inspection of the facility listed above was performed by the Environmental Health & Safety - Fire and Life Safety and the Corvallis Fire Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately and no later than the scheduled reinspection date noted with this report. If you have any questions regarding this inspection, please email Brian Lilley (EH&S - Fire and Life Safety) at brian.lilley@oregonstate.edu.

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

* Annotates a deficiency identified by the Corvallis Fire Department.

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health & Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action so that all deficiencies have been corrected prior to the reinspection date. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969.

Facilities Services Priority Codes:

Priority 1: items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: items are long term fixes that should be either added to an ongoing work list or to the capital improvement list for campus upgrades.

Comments:

Priority code	Standard in need of attention	Reg.Reference	Location	Resp	Observations & Recommendations	Date Corrected
2	Fire department connections (FDC) must be visible, identified, accessible, and must be tested and maintained. Partial building coverage shall be indicated.	2019 OFC 912	West Side:exterior	DEPT	Replace faded FDC sign on west side of building.	

Priority code	Standard in need of attention	Reg.Reference	Location	Resp	Observations & Recommendations	Date Corrected
2	Emergency lighting shall be maintained.	2019 OFC 1031.10	Various:ceiling	DEPT	Repair/maintain exit lights in locations: 1) Main stairwell top of stairs 2) Near room 65B 3) Former Joe's Burgers restaurant 4) Off The Quad restaurant by side emergency exit door 5) East ballroom	
2	Fire protection systems shall be inspected, tested and maintained in accordance with their referenced standards. Affix inspection tag to system.	2019 OFC 901.6.1	Joe's:inside	DEPT	Suppression system shall be maintained and in working condition in the former Joe's Burgers space.	
2	Approved covers shall be provided for all switch and electrical outlet boxes.	2019 OFC 604.6	Roof Access:inside	DEPT	Replace junction box covers in roof access maintenance space.	
2	Abate electrical hazard	2019 OFC 604.1	JavaStop:inside	DEPT	Repair microwave plug in JavaStop coffee shop.	
2	Discontinue use of extension cord not plugged directly into an approved receptacle. Do not chain together.	2019 OFC 604.5.1	ID Center:inside	DEPT	Discontinue chaining power strip into power strip in ID Center at main work station.	
2	Compressed gas cylinders shall be secured with one or more restraints to prevent falling.	2019 OFC 5303.5.3	Various:inside	DEPT	Secure gas cylinders with restraints in spaces: 1) Off The Quad 2) Room 32 near storage cages	