



NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY

Facility Inspected: Reser Stadium
 Inspection Date: 08/05/20 11:40 AM
 Reinspect Date:

A joint fire safety inspection of the facility listed above was performed by the Environmental Health & Safety - Fire and Life Safety Department and the Corvallis Fire Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately and no later than the scheduled reinspection date listed in the accompanying email. If you have any questions regarding this inspection, please email me. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Safety Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

* Annotates a deficiency identified by the Corvallis Fire Department..

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action so that all deficiencies have been corrected prior to the reinspection date.

Facilities Services Priority Codes:

Priority 1: items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: items are long term fixes that should be either added to an ongoing work list or to the capital improvement list for campus upgrades.

The due date is listed in the body of the Email. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Brian Lilley (EH&S - Fire and Life Safety) at brian.lilley@oregonstate.edu. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969.

Completed	Priority	Responsible Party	Location	Description	Code Reference	Notes
	2	Department	Level 1 & 3 (East Side)	Repair fire resistant coating.		
	1	Department	Concession 3	Discontinue plugging high power or heat producing appliances into power strips or extension cords. Always plug appliances into wall receptacles. - OSFM Rule & 2019 OFC 604.5.2		Discontinue use of extension cord into refrigerator.
	2	Department	Throughout	Repair/replace ceiling tiles. - 2019 OFC 703		
	1	Department	Founder's Level	Provide documentation or service fuel-fired appliance. - 2019 OFC 603		Founder's level fireplace.
	1	Facilities Services	South Stairwell (Press Boxes to Sky Boxes)	Emergency lighting shall be maintained.	2019 OFC 1031.10	
	2	Department	AT&T Room	Provide service record documentation for extinguishing system.		
	1	Department	150	A working space of not less than 36 inches in front of electrical service equipment shall be maintained. Storage of materials shall not be located within this space.	2019 OFC 604.3	
	1	Department	101	Discontinue use of extension cord not plugged directly into an approved receptacle. Do not chain together.	2019 OFC 604.5.1	
	1	Department	108	"Combustible material shall not be stored in boiler rooms, mechanical rooms, electrical equipment rooms or in fire command centers."	2019 OFC 315.3.3	Remove boxes of air filters or store in an approved orderly fashion.
	1	Department	229 and Concessions 1 & 3	Compressed gas cylinders shall be secured with one or more restraint to prevent falling.	2019 OFC 5303.5.3	

1	Department	3rd Floor Club Kitchen (East Side)	Cooking equipment hood systems need to be inspected and tagged. Prior tags should be covered or removed.	2019 OFC 901.6.1 & NFPA 17A	
2	Facilities Services	Across 301	Ensure pull station is operational.		
1	Department	317, 361, 418, Ecolab 11 (Side Kitchen Room)	"Combustible material shall not be stored in boiler rooms, mechanical rooms, electrical equipment rooms or in fire command centers."	2019 OFC 315.3.3	Ensure clear space around water heaters. Do not store items on heaters.