

Building Manager: [Debbi-Lee Mott, deb.mott@oregonstate.edu](mailto:deb.mott@oregonstate.edu)
 Assessment Date: 5/31/2022
 Assessment Number: **10576**
 Location: Student Experience Center Entire
 Reinspection date:

A joint fire safety inspection of the facility listed above was performed by the Environmental Health & Safety - Fire and Life Safety and the Corvallis Fire Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately and no later than the scheduled reinspection date noted with this report. If you have any questions regarding this inspection, please email Brian Lilley (EH&S - Fire and Life Safety) at brian.lilley@oregonstate.edu.

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

* Annotates a deficiency identified by the Corvallis Fire Department.

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health & Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action so that all deficiencies have been corrected prior to the reinspection date. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969.

Facilities Services Priority Codes:

Priority 1: items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: items are long term fixes that should be either added to an ongoing work list or to the capital improvement list for campus upgrades.

Comments:

Priority code	Standard in need of attention	Reg.Reference	Location	Resp	Observations & Recommendations	Date Corrected
2	Exit and exit access doors shall be marked by an approved exit sign readily visible from any direction of egress travel.	2019 OFC 1013.1	232:exit	FS	Provide UL listed exit sign on door from Room 232	
2	A means of egress shall be free from obstructions that would prevent its use. Combustible materials shall not be stored in exit pathways.	2019 OFC 1031.3 and 315.3.2	0010:exit	DEPT	Bins of wood chips and sawdust cannot be stored inside the building and must not be near designated egress paths in basement workshop	
2	Fire doors shall close from the full-open position and latch automatically.	2019 OFC 705.2.4	0001:entrance	FS	Adjust Doors into room 001. Doors do not fully latch when released.	
2	Stairwells shall be kept clear and not used for storage.	2019 OFC 1003.6	110:stairwell	DEPT	No storage allowed under stairway room 110. Remove combustible boxes under bench.	

Priority code	Standard in need of attention	Reg.Reference	Location	Resp	Observations & Recommendations	Date Corrected
3	Sprinklers shall be positioned and located so as to provide satisfactory performance.	NFPA 13 Chapter 9	varies:ceiling	FS	Replace/Repair sprinkler escutcheons rooms 325, 306, 250. The protective sleeves for the sprinkler heads are either missing or are starting to slide down.	
2	Maintain housekeeping of metal shavings/combustible dusts.		0010B:inside	DEPT	Dust and Wood debris MUST be cleared from basement wood shop. 	
2	Power strips, extension cords, or any other electrical cord shall not extend through walls, ceilings, floors, under doors or floor coverings, or be subject to damage.	2019 OFC 604.5	0380:inside	DEPT	Floor protection required for power strip cord on floor room 380	
2	Discontinue use of extension cord not plugged directly into an approved receptacle. Do not chain together.	2019 OFC 604.5.1	0001A:inside	DEPT	Discontinue plugging extension cords into grinder or power strip according to manufacturers instructions. Power strips need to be on the ground or mounted to the wall. They cannot be free hanging.	
3	Additional Findings:		002J:inside	DEPT	Provide non-combustible storage for plastics near kilns room 002J - 2019 OFC 603.5.1 Options could be install another metal storage cabinet or remove plastics from this room.	