

NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY



Facility Inspected: The Valley Library
 Inspection Date: 12/20/17 1:25 PM
 Reinspect Date: 12/22/17 8:00 AM

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection, please phone me at 737-3066. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Prevention Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

** Annotates a deficiency identified by OSU Environmental health and safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.

Facilities Services Priority Codes:

Priority 1: (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: (p2) items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Jim Patton (Corvallis Fire Department) at 737-3066. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969. MS Excel format is available upon request.

Completed	Priority	Responsible Party	Location	Description	Code Reference	Notes
	2	Facilities Services	On East Side of Building Near Java Entry	Clear fire hydrant		Provide a minimum of 36" clearance around fire hydrant
	2	EH&S	Near Java	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	
	2	Facilities Services	East Stairwell	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Adjust stairwell doors to self-latch upon closing
	2	Facilities Services	First Floor West Stairwell	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Adjust stairwell doors to self-latch upon closing

2	Facilities Services	Stairwell #4		NULL	Restore stairwell lighting
2	Facilities Services	Electrical "MCC" Room	"Label electrical rooms, panel(s), and circuits. Electrical circuits for fire alarm systems must be locked in the "ON" position."	"CFC 605.3.1,NFPA 72"	Cover circuit blank in circuit panel
2	Facilities Services	West Stairwell	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Adjust stairwell doors to close and self-latch
2	Facilities Services	West Stairwell	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Adjust stairwell doors to close and self-latch
2	Department			NULL	Provide documentation that the installed sound proofing material is fire resistive.
2	Facilities Services	East Stairwell	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Adjust stairwell doors to close and self-latch
2	EH&S	Special Collections Room	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	
2	Facilities Services	West Stairwell	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Adjust stairwell doors to close and self-latch
2	Facilities Services	Exterior SE Corner	"Fire protection or detection systems shall be extended, altered, or repaired as necessary to maintain protection."	CFC 901.6	Trim back vegetation to FD standpipe connection
2	Facilities Services	East Stairwell	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Adjust stairwell doors to close and self-latch