

NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY



Facility Inspected: Gilmore Hall
 Inspection Date: 02/09/18 10:28 AM
 Reinspect Date:

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection, please phone me at 737-3066. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Prevention Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

** Annotates a deficiency identified by OSU Environmental health and safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.

Facilities Services Priority Codes:

Priority 1: (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: (p2) items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Jim Patton (Corvallis Fire Department) at 737-3066. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969. MS Excel format is available upon request.

Completed	Priority	Responsible Party	Location	Description	Code Reference	Notes
	2	Facilities Services	GA Shop	"Portable Ladders are OSHA approved and in good condition, steps and side rail joints tight"	"OSHA, Division 2 requirement"	
	2	Facilities Services	GA Shop	Repair exit door/hardware.	CFC 1008	EXIT door drags on exterior ground when opened.
	1	Department	GA Shop	"Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES."	"CFC 315.3.2, 1030.3"	Move BBQ from in front of EXIT
	2	Department	GA Shop	Disconnect LPG tank from BBQ grill		
	2	EH&S	Gilmore Suite 125	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	

2	Facilities Services	GA Second Floor	Provide/maintain exit sign.	CFC 1011.1	Bad Battery
2	EH&S	G202	"Provide a 2A:10BC fire extinguisher for every 3,000 square feet, with a maximum travel distance of 75 feet. Additional requirements for hazardous areas."	"CFC 906.1, NFPA 10"	Replace undersized clean agent fire extinguisher with an approx. 5 lb. unit.
1	Department	G211	Discard toaster over with broken door.		
2	Department	G225	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	"CFC 605.4, 605.5"	
2	Department	G208	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	"CFC 605.4, 605.5"	
2	Department	G206	Maintain 30 inches clearance in front of electrical control panels.	CFC 605.3	
2	Department	G206	Laboratory Safety Quick Reference Guide posted in each lab area. (These can be obtained from EH&S)	"OSHA, Division 2 requirement"	
2	Department	G233	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	"CFC 605.4, 605.5"	
2	Department	G102A	Replace protective caps on all high pressure cylinders not actively in use.	CFC 5003.10.1	
2	Department	G103	Maintain 30 inches clearance in front of electrical control panels.	CFC 605.3	
1	Department	G103	Discontinue dispensing flammable/combustible liquids outside of an approved fume hood		
2	Department	G105	Label all chemical containers (1 gallon and larger) as to plain language contents & associated hazard. *All containers should be labeled.	CFC 2703.5.1	
2	Department	G105	Replace protective caps on all high pressure cylinders not actively in use.	CFC 5003.10.1	
2	Department	G104	Replace protective caps on all high pressure cylinders not actively in use.	CFC 5003.10.1	