

# NOTICE OF FIRE SAFETY INSPECTION

## OREGON STATE UNIVERSITY



Facility Inspected: WALDO HALL

Inspection Date: 08/08/2017

Reinspect Date:

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection, please phone me at 737-3066. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Prevention Officer, jim.patton@oregonstate.edu

**Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.**

*\* Annotates a deficiency identified by OSU Environmental health and safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.

### Facilities Services Priority Codes:

Priority 1: (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: (p2) items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Jim Patton (Corvallis Fire Department) at 737-3066. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969. MS Excel format is available upon request.

Completed?	Priority	Responsible Party	Location	Description	Code Reference	Notes
------------	----------	-------------------	----------	-------------	----------------	-------

Completed?	Priority	Responsible Party	Location	Description	Code Reference	Notes
	2	EHS	Across from 118	Extinguishers shall be visible or signed, easily accessible, mounted with the bottom not less than 4 inches nor the top more than 4 feet above the floor.	CFC 906, NFPA 10, ADA	Install a two-way sign over fire extinguisher.
	1	DEPT	Near 321	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES.	CFC 315.2.2, 1027, <a href="http://surplus.oregonstate.edu/spr">http://surplus.oregonstate.edu/spr</a>	Remove material from hallway!
	1	DEPT	0343		OFC 3807.3	Discontinue use of household fan when not in attendance.
	1	DEPT	0342		OFC 3807.3	Remove candle (on floor) from building. Burning candles is prohibited in offices on campus.

Completed?	Priority	Responsible Party	Location	Description	Code Reference	Notes
	1	DEPT	Left of 331	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES.	CFC 315.2.2, 1027, <a href="http://surplus.oregonstate.edu/spr">http://surplus.oregonstate.edu/spr</a>	Remove cabinet from hallway!
	1	DEPT	Near 334	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES.	CFC 315.2.2, 1027, <a href="http://surplus.oregonstate.edu/spr">http://surplus.oregonstate.edu/spr</a>	Remove material from hallway!
	1	DEPT	Right of 350	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES.	CFC 315.2.2, 1027, <a href="http://surplus.oregonstate.edu/spr">http://surplus.oregonstate.edu/spr</a>	Remove table from hallway!
	1	DEPT	Across from 302	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES.	CFC 315.2.2, 1027, <a href="http://surplus.oregonstate.edu/spr">http://surplus.oregonstate.edu/spr</a>	Remove table and rolling chair from hallway!

Completed?	Priority	Responsible Party	Location	Description	Code Reference	Notes
	1	DEPT	Near 231	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES.	CFC 315.2.2, 1027, <a href="http://surplus.oregonstate.edu/spr">http://surplus.oregonstate.edu/spr</a>	Remove debris from hallway!
	1	DEPT	Near 222	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES.	CFC 315.2.2, 1027, <a href="http://surplus.oregonstate.edu/spr">http://surplus.oregonstate.edu/spr</a>	Remove cabinet from hallway!
	1	DEPT	Near 282	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES.	CFC 315.2.2, 1027, <a href="http://surplus.oregonstate.edu/spr">http://surplus.oregonstate.edu/spr</a>	Remove material from hallway.
	1	FS	0248	Electrical appliances, equipment, fixtures, and facilities shall be used and installed in accordance with their listing.	CFC 605	Outlet removed. Conductors exposed (not sure if they are live). Cap and enclose.

Completed?	Priority	Responsible Party	Location	Description	Code Reference	Notes
	2	DEPT	0126	Plug power strips directly into outlet. Do not chain one to another.	CFC 605.4.2	
	1	DEPT	Near 130	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES.	CFC 315.2.2, 1027, <a href="http://surplus.oregonstate.edu/spr">http://surplus.oregonstate.edu/spr</a>	Remove chair from hallway!
	2	FS	Near 122	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Adjust fire door to self-latch
	2	FS	Near 100	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Restore hold-open device to hold door.
	2	EHS	Random Throughout	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	CFC 906.2, NFPA 10	Several fire extinguishers are due throughout building

Completed?	Priority	Responsible Party	Location	Description	Code Reference	Notes
	2	FS	Near 115A	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Adjust fire door to close tightly
	0				OFC 3807.3	