

NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY



Facility Inspected: Poultry Research Facility
 Inspection Date: 05/03/18 1:08 PM
 Reinspect Date: 06/14/18 8:00 AM

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection, please phone me at 737-3066. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Prevention Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

** Annotates a deficiency identified by OSU Environmental health and safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.

Facilities Services Priority Codes:

Priority 1: (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: (p2) items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Jim Patton (Corvallis Fire Department) at 737-3066. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969. MS Excel format is available upon request.

Completed	Priority	Responsible Party	Location	Description	Code Reference	Notes
X	2	Department	Private Residence	Ensure smoke alarms are functional, ensure portable fire extinguisher is present and current, ensure egress windows work from every bedroom.		
X	2	Department	Small Ignitable Liquid Shed	Clear vegetation around shed, and remove flammable liquid container without properly functioning lid.		
X	2	Facilities Services	Bldg. 300 - Incubator Room	"Provide cover plates on all electrical outlets, switches, and junction boxes."	CFC 605.6	Cover ceiling J-box.
X	2	Department	Bldg. 300 - Walk-in cooler	Abate Electrical Hazard	CFC 605.1	Adjust wiring to light fixture so as to secure the cord appropriately.

	2	EH&S	Bldg. 300 - Near LPG Tank	"Provide a 2A:10BC fire extinguisher for every 3,000 square feet, with a maximum travel distance of 75 feet. Additional requirements for hazardous areas."	"CFC 906.1, NFPA 10"	Provide a 10 lb. ABC fire extinguisher within 50' of LPG tank
X	2	Department	Bldg. 100 - Breakroom	Discontinue suspending power strip.		
X	2	Department	ALL Buildings	Recommend providing keyed door hardware on all exterior entry doors.		
X	2	Department	ALL Buildings	Remove accumulation of waste material adjacent to the exterior of the building.	CFC 304.1	Closely mow or remove vegetation at least 5 feet back from each building
	2	EH&S	West Side of Bldg. 100	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	
	2	Department	Throughout Site	"Remove" combustible vegetation from around ALL LPG tanks, at least 10' around each tank shall be provided.		
	2	Facilities Services	Entry off of Harrison	Address identification must be visible from the street (new installations - minimum number height = 6 inches).	CFC 505.1	Provide 6" address numbers visible from Harrison.