

Priority code	Standard in need of attention	Reg.Reference	Location	Resp	Observations & Recommendations	Date Corrected
2	Approved covers shall be provided for all switch and electrical outlet boxes.	2019 OFC 604.6	338:Left-Center Ceiling	FS	Provide cover plates for open junction boxes and/or exposed wires.	
1	A working space of not less than 36 inches in front of electrical service equipment shall be maintained. Storage of materials shall not be located within this space.	2019 OFC 604.3.1	0224:inside	DEPT	Move recycle bin in front of electrical panel.	3/25/2021
2	Power strips, extension cords, or any other electrical cord shall not extend through walls, ceilings, floors, under doors or floor coverings, or be subject to damage.	2019 OFC 604.5	0114:inside	DEPT	Discontinue mounting power strips with zip-ties. Mount according to manufacturer's instructions.	
1	Discontinue use of extension cord not plugged directly into an approved receptacle. Do not chain together.	2019 OFC 604.5.1	Throughout:inside	DEPT	Discontinue plugging power strips and/or extension cords into one another. Rooms: 310 132 SE Corner	3/25/2021
1	Combustible material shall not be stored in boiler rooms, mechanical rooms, electrical equipment rooms or in fire command centers.	2019 OFC 315.3.3	Throughout:.	DEPT	Discontinue storing items in mechanical breezeway: 2nd floor 3rd floor	3/25/2021
2	Containers of hazardous materials located on the floor shall be placed in an approved secondary container.	2019 OFC 5004.2	0432:inside	DEPT/EHS	Place oil containers in secondary containment. 	3/25/2021
2	Additional Findings:		0436:inside	FS FS EHS	Replace covers on water chiller machine to reduce risk of electrical shock or fire. - 2019 OFC 605.6	
2	Additional Findings:		Throughout:.	FS FS EHS	Replace ceiling covers: Outside 400 Outside 320 (COMPLETED) 116 (COMPLETED) 104	
2	Additional Findings:		Throughout:entrance	FS FS EHS	Provide NFPA 704 placard for rooms: 118E 118D	