



NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY

Facility Inspected: Weniger Hall
 Inspection Date: 03/19/20 2:13 PM
 Reinspect Date:

A joint fire safety inspection of the facility listed above was performed by the Environmental Health & Safety - Fire and Life Safety Department and the Corvallis Fire Department. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately and no later than the scheduled reinspection date listed in the accompanying email. If you have any questions regarding this inspection, please email me. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Safety Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

* Annotates a deficiency identified by the Corvallis Fire Department..

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action so that all deficiencies have been corrected prior to the reinspection date.

Facilities Services Priority Codes:

Priority 1: items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: items are long term fixes that should be either added to an ongoing work list or to the capital improvement list for campus upgrades.

The due date is listed in the body of the Email. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Brian Lilley (EH&S - Fire and Life Safety) at brian.lilley@oregonstate.edu. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969.

| Completed | Priority | Responsible Party | Location | Description | Code Reference | Notes |
|-----------|----------|---------------------|--------------------------|---|----------------|--|
| | 1 | Department | 212 | Plug power strips directly into outlet. Do not chain one to another. | CFC 605.4.2 | |
| | 1 | Department | 206 | Plug power strips directly into outlet. Do not chain one to another. | CFC 605.4.2 | |
| | 1 | Department | 381 & 383 | Discontinue hanging decorative lights around ceiling tile frames. | | |
| | 1 | Department | 322 (Studio) | Plug power strips directly into outlet. Do not chain one to another. | CFC 605.4.2 | |
| | 1 | Department | Throughout | Be sure to clean personal air conditioning filters every few months. | | General reminder. |
| | 1 | Department | 324 | Remove combustibles by egress door. | | |
| | 1 | Department | 322 | Provide secondary containment for methanol on floor. | | |
| | 1 | Facilities Services | NW Main Exit (1st Floor) | Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided. | CFC 703.2 | Right side door does not open properly. |
| | 1 | Facilities Services | 139 | "Provide cover plates on all electrical outlets, switches, and junction boxes." | CFC 605.6 | |
| | 1 | Department | 100B | Plug power strips directly into outlet. Do not chain one to another. | CFC 605.4.2 | |
| | 1 | Department | 125A | Plug power strips directly into outlet. Do not chain one to another. | CFC 605.4.2 | Use an approved power strip with timer similar to the one in the main lab. |

| | | | | | |
|---|---------------------|-----------------------|--|--------------------|--|
| 1 | Department | 416 | Maintain 30 inches clearance in front of electrical control panels. | CFC 605.3 | |
| 1 | Department | 414 (Throughout) | Remove containers off of floor. | | |
| 1 | Department | 414 | Maintain 30 inches clearance in front of electrical control panels. | CFC 605.3 | Relocate flammable cabinet in front of electrical panel. |
| 2 | Facilities Services | Across From 404 | Remove phone from wall. | | Phone does not work and should be removed to avoid confusion during an emergency. |
| 1 | Department | 405 | Maintain 30 inches clearance in front of electrical control panels. | CFC 605.3 | |
| 1 | Facilities Services | 426 | "Provide cover plates on all electrical outlets, switches, and junction boxes." | CFC 605.6 | |
| 1 | Department | 424 | Maintain 30 inches clearance in front of electrical control panels. | CFC 605.3 | |
| 1 | Department | 420 | Secure compressed gas cylinders. | CFC 3003.3.3 | |
| 1 | Facilities Services | 422 | "Provide cover plates on all electrical outlets, switches, and junction boxes." | CFC 605.6 | Wires exposed near entrance. |
| 1 | Department | 422 | Maintain 30 inches clearance in front of electrical control panels. | CFC 605.3 | |
| 1 | Department | 504 | Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable. | "CFC 605.4, 605.5" | Discontinue using extension cord for freezer. |
| 1 | DEPT/FS | 504 | "Cords shall not be affixed to, or extend through, walls, ceilings, floors, under doors, and shall not be subject to physical damage." | CFC 605.4.3 | Replace frayed cord near autoclave. |
| 1 | Department | 577 | Plug power strips directly into outlet. Do not chain one to another. | CFC 605.4.2 | |
| 1 | Department | 557 | Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable. | "CFC 605.4, 605.5" | Discontinue use of orange extension cord. |
| 1 | Department | 538 | "Provide approved cabinet for more than 10 gallons of flammable/combustible liquids. Maximum 3 cabinets, 120 gal. per cabinet." | CFC 5003.8.7 | Relocate ethanol into flammable cabinet. |
| 1 | Department | 553 | Plug power strips directly into outlet. Do not chain one to another. | CFC 605.4.2 | Also, discontinue use of light above board or professionally service/install. |
| 1 | Facilities Services | 534 | Open breakers in electrical panel. | | |
| 1 | Department | 545 | Remove combustible waste around panel. | | |
| 1 | Department | 545 | Move cord out of egress path. | | Remove cord or provide cord protection cover. |
| 1 | Department | 520 | Remove AC unit connected to fume hood ducting. | | Either remove AC unit or provide documentation air handling for fume hood supports unit. |
| 1 | Department | 529 | Plug power strips directly into outlet. Do not chain one to another. | CFC 605.4.2 | |
| 2 | Facilities Services | Throughout | Fire extinguisher cabinets in hallways need handles. | | |
| 1 | Facilities Services | 514 | "Provide cover plates on all electrical outlets, switches, and junction boxes." | CFC 605.6 | |
| 1 | Department | 514 | Attach smoke alarm per manufacturer's instructions. | | |
| 1 | Facilities Services | 635 (Throughout Room) | "Provide cover plates on all electrical outlets, switches, and junction boxes." | CFC 605.6 | |
| 1 | Department | 627C | Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable. | "CFC 605.4, 605.5" | |