

NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY



Facility Inspected: Farm Service
 Inspection Date: 06/04/18 3:18 PM
 Reinspect Date: 07/25/18 8:00 AM

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection, please phone me at 737-3066. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Prevention Officer, jim.patton@oregonstate.edu

Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

** Annotates a deficiency identified by OSU Environmental health and safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.

Facilities Services Priority Codes:

Priority 1: (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

Priority 2: (p2) items should be corrected within the five-week period before the scheduled reinspections.

Priority 3: (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Jim Patton (Corvallis Fire Department) at 737-3066. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969. MS Excel format is available upon request.

Completed	Priority	Responsible Party	Location	Description	Code Reference	Notes
	2	Department	Farm Services Office	Provide approved outlet and fuse protected power strip to accept unit. No homemade cords or ground cheater plugs		
X	2	EH&S	Steer-A-Year Building	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	
X	2	EH&S	Swine Center (Near LPG Tank)	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	
X	2	Department	Swine Center	Residence: Ensure smoke alarms are functional, Ensure egress windows are functional, ensure a portable fire extinguisher has been mounted and is current.		

	2	Department	3640 Campus Way Buildings	Replace private padlock with University padlock.		
X	2	EH&S	3640 Campus Way Buildings	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	
X	2	EH&S	3620 Campus Way Buildings	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	
X	2	Department	Bldg. 354 (Along Campus Way) Crop Science	Label all chemical containers (1 gallon and larger) as to plain language contents & associated hazard. *All containers should be labeled.	CFC 2703.5.1	
	2	Department	Bldg. 354 (Along Campus Way) Crop Science	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	"CFC 605.4, 605.5"	Provide additional outlets or approved power strips.
	2	Department	Farm Services	Cut and remove vegetation 10 feet around elevated diesel tank		
X	2	Department	Farm Services Shop	Wood burning stove: Have stove & installation verified and vent properly cleaned.		
X	2	Department	Farm Services Breakroom	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	"CFC 605.4, 605.5"	To coffee maker
X	2	Department	Farm Services Breakroom	"Cords shall not be affixed to, or extend through, walls, ceilings, floors, under doors, and shall not be subject to physical damage."	CFC 605.4.3	Discontinue running extension cord through wall
X	2	Department	Farm Services Shop (office)	Abate Electrical Hazard	CFC 605.1	Don't chain power strips and remove ground bypass adapter, etc....
X	2	DEPT/EHS	Farm Services Shop	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	Coordinate with EH&S fire extinguisher staff to service additional fire extinguishers on floor.
X	2	Department	Farm Services Quonset Building	Provide 36" clearance around kerosene tank or empty/ remove tank (label appropriately).		
X	2	EH&S	Throughout Farm Services Complex	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	
X	2	EH&S	Near Elevated Diesel Tank	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	
X	2	EH&S	3524 Campus Way (Livestock Pavillion)	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydrotest every 12 years.	"CFC 906.2, NFPA 10"	