

**NOTICE OF FIRE SAFETY INSPECTION OREGON STATE UNIVERSITY**



Facility Inspected: Linus Pauling Science Center  
 Inspection Date: 06/04/19 4:25 PM  
 Reinspect Date: 07/15/19 8:00 AM

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection, please phone me at 737-3066. Thank you for your cooperation and support for fire safety. Jim Patton, Fire Prevention Officer, jim.patton@oregonstate.edu

**Note: Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.**

*\* Annotates a deficiency identified by OSU Environmental health and safety Department. Direct any questions regarding these items to that office (737-2273).*

*Indicated on the report are items which should be correct by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.*

**Facilities Services Priority Codes:**

**Priority 1:** (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.

**Priority 2:** (p2) items should be corrected within the five-week period before the scheduled reinspections.

**Priority 3:** (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

*The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Jim Patton (Corvallis Fire Department) at 737-3066. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department, contact the Work Coordination Center at ext. 7-2969. MS Excel format is available upon request.*

Completed	Priority	Responsible Party	Location	Description	Code Reference	Notes
X	2	Facilities Services	Basement Mechanical Room	Power inverter appears to be due		
X	2	EH&S	Basement Mechanical Room	Provide a current inspection tag on pump		Provide correct bracket for fire extinguisher on floor
X	2	Department	Near 260A (or 268)	Abate Electrical Hazard	CFC 605.1	Plug refrigerator and fume hood into wall receptacle not power strip.
	2	Department	Room 266	Secure table top drill (OSHA Requirement)		
X	1	Department	Near 248A and Nearby	Discontinue practice of storing breakable chemical containers on floor.	CFC 2703.9.2	

X	2	Facilities Services	Room 223	Fire doors/smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided.	CFC 703.2	Adjust fire door to self-latch
X	2	Recycling	Break room Near 479	Combustible recycling containers shall not be placed in exitways. Containers may be placed in non hazardous rooms.	CFC 319.5	Remove bag stand
X	2	EH&S	Penthouse (West End)	"Extinguishers shall be visible or signed, easily accessible, mounted with the bottom not less than 4 inches nor the top more than 4 feet above the floor."	"CFC 906.9, NFPA 10, ADA"	Provide correct bracket to mount fire extinguisher.